

REDUCING BUSH

REDUCING BUSH
 spigot for solvent welding (1st d
 of reference) socket for solvent
 welding (reduced d₁)

REDUCTION SIMPLE
 male à coller sur le 1er d de référence,
 femelle à coller sur le d₁
 réduit




Fig. A




Fig. B

	d x d ₁	L	Z	Fig	g
	1/2 x 3/8	16,5	2,0	A	3,0
	3/4 x 1/2	19,5	3,0	A	5,5
	1 x 1/2	22,5	6,5	A	18,0
	1 x 3/4	22,5	3,0	A	10,0
	1 1/4 x 1	27,0	4,0	A	19,0
	1 1/2 x 3/4	30,0	10,0	B	40,0
	1 1/2 x 1	30,0	7,5	A	42,0
	1 1/2 x 1 1/4	31,0	4,0	A	20,0
	2 x 3/4	36,0	16,5	B	75,0
	2 x 1	36,0	7,0	B	50,0
	2 x 1 1/2	38,0	7,0	B	50,0
	2 1/2 x 2	43,5	7,5	A	100,0
	3 x 1 1/2	50,5	20,5	B	200,0
	3 x 2	51,0	13,0	B	167,0
	3 x 2 1/2	50,5	7,0	A	125,0
	4 x 2	63,0	27,0	B	370,0
	4 x 3	63,0	12,0	A	331,0
	*6 x 4	90,0	27,0	B	972,0
	*8 x 6	115,5	25,5	B	1400,0

*class D *classe D